Spill Prevention Control and Countermeasure Inspection Findings, Alleged Violations, and Proposed Penalty Form

(Note: Do not use this form if there is no secondary containment)

These Findings, Alleged Violations and Penalties are issued by EPA Region 6 under the authority vested in the Administrator of EPA by Section 311(b)(6)(B)(I) of the Clean Water Act, as amended by the Oil Pollution Act of 1990.

Company Name	Docket Number:		<u>_</u>
Chaparral Energy	CWA-06-2015-4304	• /	UNITED STATES
Facility Name	Date		
SBU (B) R & S Tank Battery	10/22/2014		BANNAL AROTECTIONS
Address	Inspection Number		A STATE OF THE STA
701 Cedar Lake Blvd.	FY-INSP-SPCC-OK-20	15-00009	THING POSTECTION
City:	Inspectors Name:		NAME OF THE PARTY
Oklahoma City	Tom McKay		1
State: Zip Code:	EPA Approving Official:		
OK 73114-7806	Donald P. Smith		
Contact:	Enforcement Contacts:		
Mr. Shawn Wiley (405) 429-4329	Misty Ward (214)665-64	18	
No Spill Prevention Control and Countermeasure			•
Plan not certified by a professional engineer- 112.	3(d)	*****************	450.00
Certification lacks one or more required elements	- 112.3(d)(1)		100.00
No management approval of plan- 112.7		•••••	450.00
Plan not maintained on site (if facility is manned	at least 4 hrs/day) or not av	ailable for rev	iew- 112.3(e)(1)300.00
No evidence of five-year review of plan by owner	operator- 112.5(b)	••••••	75.00
No plan amendment(s) if the facility has had a char or maintenance which affects the facility's dischar			75.00
Amendment(s) not certified by a professional engi	ineer- 112.5(c)		150.00
	·	94	190172

Plan does not follow sequence of the rule and/or cross-reference not provided- 112.7	150.00
Plan does not discuss additional procedures/methods/equipment not yet fully operational- 112.7	75.00
Plan does not discuss alternative environmental protection to SPCC requirements- 112.7(a)(2)	200.00
Plan has inadequate or no facility diagram- 112.7(a)(3)	75.00
Inadequate or no listing of type of oil and storage capacity layout of containers- 112.7(a)(3)(i)	50.00
Inadequate or no discharge prevention measures- 112.7(a)(3)(ii)	. 50.00
Inadequate or no description of drainage controls- 112.7(a)(3)(iii)	. 50.00
Inadequate or no description of countermeasures for discharge discovery, response and cleanup- 112.7(a)(3)	(iv) 50.00
Recovered materials not disposed of in accordance with legal requirements- 112.7(a)(3)(v)	50.00
No contact list & phone numbers for response & reporting discharges- 112.7(a)(3)(vi)	50.00
Plan has inadequate or no information and procedures for reporting a discharge- 112.7(a)(4)	100.00
Plan has inadequate or no description and procedures to use when a discharge may occur- 112.7(a)(5)	150.00
Inadequate or no prediction of equipment failure which could result in discharges- 112.7(b)	150.00
Plan does not discuss and facility does not implement appropriate containment/diversionary structures/equip (including truck transfer areas) 112.7(c)	
- If claiming impracticability of appropriate containment/diversionary structures:	
Impracticability has not been clearly denoted and demonstrated in plan- 112.7(d)	100.00
No contingency plan- 112.7(d)(1)	150.00
No written commitment of manpower, equipment, and materials- 112.7(d)(2)	150.00
No periodic integrity and leak testing, if impracticability is claimed - 112.7(d)	150.00
Plan has no or inadequate discussion of general requirements not already specified- 112.7(a)(1)	75.00
QUALIFIED FACILITY REQUIREMENTS: 112.6	
Qualified Facility: No Self certification- 112.6(a)	450.00
Qualified Facility: Self certification lacks required elements- 112.6(a)	100.00
Qualified Facility: Technical amendments not certified- 112.6(b)	150.00
Qualified Facility: Un-allowed deviations from requirements- 112.6(c)	100.00
Qualified Facility: Environmental Equivalence or Impracticability not certified by PE- 112.6(d)	350.00

WRITTEN PROCEDURES AND INSPECTION RECORDS 112.7(e)

The Plan does not include inspections and test procedures in accordance with 40 CFR Part 112 - 112.7(e)	75.00
Inspections and tests required by 40 CFR Part 112 are not in accordance with written procedures developed for the facility- 112.7(e)	75.00
No Inspection records were available for review - 112.7(e)	200.00
Written procedures and/or a record of inspections and/or customary business records:	
Are not signed by appropriate supervisor or inspector- 112.7(e)	75.00
Are not maintained for three years- 112.7(e)	75.00
 PERSONNEL TRAINING AND DISCHARGE PREVENTION PROCEDURES 112.7(f)	
No training on the operation and maintenance of equipment to prevent discharges- 112.7(f)(1)	75.00
No training on discharge procedure protocols- 112.7(f)(1)	75.00
No training on the applicable pollution control laws, rules, and regulations- 112.7(f)(1)	75.00
Training records not maintained for three years- 112.7(f)	75.00
No training on the contents of the SPCC Plan- 112.7(f)(1)	
No designated person accountable for spill prevention- 112.7(f)(2)	75.00
Spill prevention briefings are not scheduled and conducted periodically- 112.7(f)(3)	75.00
Plan has inadequate or no discussion of personnel and spill prevention procedures- 112.7(f)	75.00
FACILITY TANK CAR AND TANK TRUCK LOADING/UNLOADING 112.7(c) and/or (h-j)	
Inadequate containment for Loading Area (not consistent with 112.7(c)) - 112.7(c)	400.00
Inadequate secondary containment, and/or rack drainage does not flow to catchment basin, treatment system, or quick drainage system- 112.7(h)(1).	750.00
Containment system does not hold at least the maximum capacity of the largest single compartment of any tank car or tank truck- 112.7(h)(1).	450.00
There are no interlocked warning lights, or physical barrier system, or warning signs, or vehicle brake interlock system to prevent vehicular departure before complete disconnect from transfer lines- 112.7(h)(2)	300.00
There is no inspection of lowermost drains and all outlets prior to filling and departure of any tank car or tank truck- 112.7(h)(3)	150.00
Plan has inadequate or no discussion of facility tank car and tank truck loading/unloading rack -112.7(j)	. :

QUALIFIED OIL OPERATIONAL EQUIPMENT 112.7(k)

Ē	Failure to establish and document procedures for inspections or a monitoring program to detect equipment fair a discharge- 112.7(k)(2)(i)	ilure d/or 150.00
	Failure to provide an oil spill contingency plan- 112.7(k)(2)(ii)(A)	150.00
	No written commitment of manpower, equipment, and materials- 112.7(k)(2)(ii)(B)	150.00
	OIL PRODUCTION FACILITY DRAINAGE 112.9(b)	, ·
	Drains for the secondary containment systems at tank batteries and separation and central treating areas are not closed and sealed at all times except when uncontaminated rainwater is being drained- 112.9(b)(1)	600.00
	Prior to drainage of diked areas, rainwater is not inspected, valves opened and resealed under responsible supervision and records kept of such events- 112.9(b)(1)	450.00
	Accumulated oil on the rainwater is not removed and returned to storage or disposed of in accordance with legally approved methods- 112.9(b)(1)	300.00
	Field drainage system (drainage ditches and road ditches), oil traps, sumps and/or skimmers are not regularly inspected and/or oil is not promptly removed- 112.9(b)(2)	300.00
	Inadequate or no records maintained for drainage events- 112.7	75.00
	Plan has inadequate or no discussion or procedures for facility drainages- 112.7(a)(1)	75.00
	OIL PRODUCTION FACILITY BULK STORAGE CONTAINERS 112.9(c)	:
	Plan has inadequate or no risk analysis and/or evaluation of field-constructed aboveground tanks for brittle fracture- 112.7(i)	75.00
	Failure to conduct evaluation of field-constructed aboveground tanks for brittle fracture- 112.7(i)	300.00
	Container material and construction are not compatible with the oil stored and the conditions of storage- 112.9(c)(1)	450.00
	Size of secondary containment appears to be inadequate for containers and treating facilities- 112.9(c)(2)	750.00
	Excessive vegetation which affects the integrity of the containment- 112.9(c)(2)	150.00
	Walls of containment system are slightly eroded or have low areas- 112.9(c)(2)	300.00
	Secondary containment materials are not sufficiently impervious to contain oil- 112.9(c)(2)	375.00
	Visual inspections of containers, foundation and supports are not conducted periodically for deterioration and maintenance needs- 112.9(c)(3)	450.00

	Bank battery installations are not in accordance with good engineering practice because none of the following are present- 112.9(c)(4)	450.00
	 Adequate tank capacity to prevent tank overfill- 112.9(c)(4)(i), or Overflow equalizing lines between the tanks- 112.9(c)(4)(ii), or Vacuum protection to prevent tank collapse- 112.9(c)(4)(ii), or High level alarms to generate and transmit an alarm signal where facilities are part of a computer control system- 112.9(c)(4)(iv). 	
	Plan has inadequate or no discussion of bulk storage tanks- 112.7(a)(1)	75.00
,	FACILITY TRANSFER OPERATIONS, OIL PRODUCTION FACILITY 112.9(D)	
	Above ground valves and pipelines are not examined periodically on a scheduled basis for general condition (includes items, such as: flange joints, valve glands 2 nd bodies, drip pans, pipeline supports, bleeder and gauge valves, polish rods/stuffing box.)- 112.9(d)(1)	450.00
	Brine and saltwater disposal facilities are not examined often- 112.9(d)(2)	450.00
	Inadequate or no flowline maintenance program (includes: examination, corrosion protection, flowline replacement)- 112.9(d)(3)	450.00
	Plan has inadequate or no discussion of oil production facilities- 112.7(a)(1)	75.00
	Plan does not include a signed copy of the Certification of the Applicability of the Substantial Harm Criteria p CFR Part- 112.20(e) (Do not use this if FRP subject, go to traditional enforcement)	

TOTAL \$900.00

CERTIFICATE OF SERVICE

I certify that the original and one copy of the foregoing "Consent Agreement and Final Order," issued pursuant to 40 C.F.R. 22.13(b), was filed on _/-/-y__, 2015, with the Regional Hearing Clerk, U.S. EPA Region 6, 1445 Ross Avenue, Dallas, TX 75202-2733; and that on the same date a copy of the same was sent to the following, in the manner specified below:

NAME: Shawn Wiley

ADDRESS: 701 Cedar Lake Blvd.

Oklahoma City, OK 73114-7806

Frankie Markham

OPA Enforcement Administrative Assistant